





1-888-DIAL-1ST
 2340 MONUMENTAL AVENUE
 BALTIMORE, MD 21227

TCC
 Incident# 47

Priority 2: Repair ASAP



Location:
Lower Red, Control Room Closet
Equipment:
PP3, Circuit 3
Problem:
Temperature in fuse and connection
Recommendation:
Replace fuse and check connections



Object Parameter	Value
File Name	PP3_Circuit_3
Emissivity	0.70
Humidity	50%
Distance	1.5
Ambient	76.6°F
MaxTemp	166.8°F
MinTemp	70.0°F
Created Date	Thursday, April 13, 2006
Created Time	11:03:24 AM
Remark	

Corrective Action Taken:	Description:
Date:	Signed: